


ECE 404-TD / 504-TD

ST: T&D APPLICATIONS OF
VOLTAGE SOURCE CONVERTERS

SESSION no. 30



→ 3φ system

→ ① AC current reference

tracking → controller design
→ switching frequency

② 3 currents → 2 are independent
→ 3 controllers

• Typically controllers work in reference frame transformed

↳ From ABC domain

→ many ways to implement transformations and choose references

→ Two axis transformations

→ Related to the Park's Transformation
→ really are instances of applying it

Two Axis Transformation

Imitation Measured Currents:

Define array of time and define angular frequency:

→ $t := 0 \text{sec}, 0.0001 \text{sec} \dots \frac{6}{60 \text{Hz}}$

$\omega_0 := 2 \cdot \pi \cdot 60 \text{Hz}$ $\omega(t) := \omega_0$

Voltage as a function of time

$V_{\text{mag}} := 15 \text{kV}$ $v_a(t) := \sqrt{2} \cdot V_{\text{mag}} \cdot \cos(\omega(t) \cdot t)$

$v_b(t) := \sqrt{2} \cdot V_{\text{mag}} \cdot \cos(\omega(t) \cdot t - 120 \text{deg})$

$v_c(t) := \sqrt{2} \cdot V_{\text{mag}} \cdot \cos(\omega(t) \cdot t + 120 \text{deg})$

Transform measured ^{voltage} currents to the stationary dq0 (αβ) reference frame:

- Use equations from the Clarke Transformation instead of matrix for now

$v_{ds}(t) := \frac{2}{3} \cdot (v_a(t) - 0.5 \cdot v_b(t) - 0.5 \cdot v_c(t))$

↳ or the αβ transform

$v_{qs}(t) := \frac{(v_b(t) - v_c(t))}{\sqrt{3}}$ Q axis 180 out of phase with some definitions

or d axis

$v_{os} = (v_a(t) + v_b(t) + v_c(t)) \cdot k = 0$

L31 3/12
137

Option 1: for a 3 ϕ current regulation

use α β transformation

→ Regulator for $i_a(t)$

and $i_b(t)$ β

- 2 controllers


- 2 independent variables

→ $i_0 = 0$ since no ground connection


→ Disadvantages - requires

AC signal tracking

6/5/13
137



Transformed voltages (not that $v_{ds}(t)$ in phase with $v_a(t)$)



Both
60 Hz

$\theta_r(t) := 2 \cdot \pi \cdot 60.0 \text{ Hz} \cdot t$ → typically, this is calculated from measurements on AC system

- Now apply rotating reference frame transformation in steps

$v_{dr1}(t) := v_{ds}(t) \cdot \cos(\theta_r(t))$

→ Phase locked loop to track AC system frequency


$$v_{dr2}(t) := v_{qs}(t) \cdot \sin(\theta_r(t))$$

$$v_{dr}(t) := v_{dr1}(t) + v_{dr2}(t)$$

$$v_{qr1}(t) := v_{ds}(t) \cdot \sin(\theta_r(t))$$

$$v_{qr2}(t) := v_{qs}(t) \cdot \cos(\theta_r(t))$$

$$v_{qr}(t) := -v_{qr1}(t) + v_{qr2}(t)$$



that can control ω constant
terms for v_{dr} , v_{qr} , i_{dr} , i_{qr}

→ 2 control loops

→ one for i_{dr}

one for i_{qr}

} Transform reference
& measurements
for feedback
control

L31 7/10/13

University of Idaho


control loop output
will be converted back to
ABC from for input to
~~fast~~ firing pulse circuit

d-axis }
q-axis } - mostly decoupled
 } in controller
 } - If you have 2 control
 } objectives in outer control

converter controls

$|V| \rightarrow \text{balanced } \phi \rightarrow \frac{dV}{dt} \rightarrow Q_{inj}$

and P_{inj}




Or if we redefine our reference angle:


$$V_{0\alpha\beta}(t) := P(0) \cdot \begin{pmatrix} v_a(t) \\ v_b(t) \\ v_c(t) \end{pmatrix}$$

α-β transf

$$\frac{v_{ds}(t)}{V_{0\alpha\beta}(t)_1}$$



$$\frac{v_{qs}(t)}{V_{0\alpha\beta}(t)_2}$$



L31 90/12

Now add some currents:

$$I_{\text{mag}} := 500\text{A}$$


$$i_a(t) := \sqrt{2} \cdot I_{\text{mag}} \cdot \cos(\omega(t) \cdot t - 30\text{deg})$$

$$i_b(t) := \sqrt{2} \cdot I_{\text{mag}} \cdot \cos(\omega(t) \cdot t - 150\text{deg})$$

$$i_c(t) := \sqrt{2} \cdot I_{\text{mag}} \cdot \cos(\omega(t) \cdot t + 90\text{deg})$$



$$I_{0dq}(t) := P(t) \cdot \begin{pmatrix} i_a(t) \\ i_b(t) \\ i_c(t) \end{pmatrix}$$

$$I_{0\alpha\beta}(t) := P(0) \cdot \begin{pmatrix} i_a(t) \\ i_b(t) \\ i_c(t) \end{pmatrix}$$



L3 10/13

Lqr



Now calculate real and reactive power

$\underline{MW} := 1000kW$ $MVA := MW$ $MVAR := MW$

- Phasor form first:

$V_a := V_{mag} \cdot e^{j \cdot 0deg}$

$I_a := I_{mag} \cdot e^{-j \cdot 30deg}$


$P_{3ph} := 3 \cdot \text{Re}(V_a \cdot \bar{I}_a)$ $P_{3ph} = 19.486 MW$

$Q_{3ph} := 3 \cdot \text{Im}(V_a \cdot \bar{I}_a)$ $Q_{3ph} = 11.25 MW$

- Now in DQ reference frames:

$P_{0dq}(t) := \frac{3}{2} \cdot (V_{0dq}(t)_0 \cdot I_{0dq}(t)_0 + V_{0dq}(t)_1 \cdot I_{0dq}(t)_1 + V_{0dq}(t)_2 \cdot I_{0dq}(t)_2)$

- Note: we need the 3/2 term because of 2/3 constant in transformation matrix.
- This will differ if use SQRT(2/3)



2/3/12
127

$$V_q \cdot I_d - V_d \cdot I_q$$

$$Q_{0dq}(t) := \frac{3}{2} \cdot (V_{0dq}(t)_2 \cdot I_{0dq}(t)_1 - V_{0dq}(t)_1 \cdot I_{0dq}(t)_2)$$

- Note: we need the 3/2 term because of 2/3 constant in transformation matrix.
- This will differ if use SQRT(2/3)

