


ECE 404-TD / 504-TD

ST: T&D APPLICATIONS OF
VOLTAGE SOURCE CONVERTERS

SESSION no. 30



→ 3 ϕ system

→ (1) AC current reference

tracking → controller design
→ switching frequency

(2) 3 currents → 2 are independent
→ 3 controllers

• Typically controllers work in reference frame transformed

↳ From ABC domain

→ many way to implement transformations and choose references

→ Two axis transformations

→ Related to the Park's Transformation
→ really are instances of applying it

Two Axis Transformation

Imitation Measured Currents:

Define array of time and define angular frequency:

→ $t := 0 \text{sec}, 0.0001 \text{sec} \dots \frac{6}{60 \text{Hz}}$ *Δt*

$\omega_0 := 2 \cdot \pi \cdot 60 \text{Hz}$ $\omega(t) := \omega_0$

Voltage as a function of time

$V_{\text{mag}} := 15 \text{kV}$ $v_a(t) := \sqrt{2} \cdot V_{\text{mag}} \cdot \cos(\omega(t) \cdot t)$

$v_b(t) := \sqrt{2} \cdot V_{\text{mag}} \cdot \cos(\omega(t) \cdot t - 120 \text{deg})$

$v_c(t) := \sqrt{2} \cdot V_{\text{mag}} \cdot \cos(\omega(t) \cdot t + 120 \text{deg})$

Transform measured currents to the stationary dq0 ($\alpha\beta$) reference frame:

- Use equations from the Clarke Transformation instead of matrix for now

$v_{\text{ds}}(t) := \frac{2}{3} \cdot (v_a(t) - 0.5 \cdot v_b(t) - 0.5 \cdot v_c(t))$

or the $\alpha\beta$ transform

$v_{\text{qs}}(t) := \frac{(v_b(t) - v_c(t))}{\sqrt{3}}$ Q axis 180 out of phase with some definitions

or d axis

$v_{\text{os}} = (v_a(t) + v_b(t) + v_c(t)) \cdot k = 0$

L31 3/13

Option 1: for a 3 ϕ current regulation

use α β transformation

→ Regulator for $i_\alpha(t)$

and $i_\beta(t)$ β

- 2 controllers


- 2 independent variables

→ $i_0 = 0$ since no ground connection


→ Disadvantage - requires

AC signal tracking

6/15/17



Transformed voltages (not that $v_{ds}(t)$ in phase with $v_a(t)$)



$\theta_r(t) := 2 \cdot \pi \cdot 60.0 \text{ Hz} \cdot t$ → typically, this is calculated from measurements on AC system

- Now apply rotating reference frame transformation in steps

$v_{dr1}(t) := v_{ds}(t) \cdot \cos(\theta_r(t))$

→ Phase locked loop to track AC system frequency

4/9/17


$$v_{dr2}(t) := v_{qs}(t) \cdot \sin(\theta_r(t))$$

$$v_{dr}(t) := v_{dr1}(t) + v_{dr2}(t)$$

$$v_{qr1}(t) := v_{ds}(t) \cdot \sin(\theta_r(t))$$

$$v_{qr2}(t) := v_{qs}(t) \cdot \cos(\theta_r(t))$$

$$v_{qr}(t) := -v_{qr1}(t) + v_{qr2}(t)$$



can control constant
terms for v_{dr} , v_{qr} , i_{dr} , i_{qr}

→ 2 control loops

→ one for i_{dr}

one for i_{qr}

} Transform reference
& measurements
for feedback
control

L317 6/13

University of Idaho

control loop output

will be converted back to

ABC frame for input to

~~IGBT~~ firing pulse circuit

d-axis

}

- mostly decoupled

in controller


q-axis

- If you have 2 control objectives in outer control

converter controls

$|V| \rightarrow$ balanced $3\phi \xrightarrow{0.5} Q_{inj}$

and P_{inj}



$2 i_{Bref}$


Or if we redefine or reference angle:

$$V_{0\alpha\beta}(t) := P(0) \cdot \begin{pmatrix} v_a(t) \\ v_b(t) \\ v_c(t) \end{pmatrix}$$


L31 90/12

α -B transf

$v_{ds}(t)$
 $V_{0\alpha\beta}(t)_1$



$v_{qs}(t)$
 $V_{0\alpha\beta}(t)_2$



Now add some currents:

$I_{mag} := 500A$


$i_a(t) := \sqrt{2} \cdot I_{mag} \cdot \cos(\omega(t) \cdot t - 30deg)$

$i_b(t) := \sqrt{2} \cdot I_{mag} \cdot \cos(\omega(t) \cdot t - 150deg)$



$i_c(t) := \sqrt{2} \cdot I_{mag} \cdot \cos(\omega(t) \cdot t + 90deg)$

$I_{0dq}(t) := P(t) \cdot \begin{pmatrix} i_a(t) \\ i_b(t) \\ i_c(t) \end{pmatrix}$

$I_{0\alpha\beta}(t) := P(0) \cdot \begin{pmatrix} i_a(t) \\ i_b(t) \\ i_c(t) \end{pmatrix}$



L31 10/13



Now calculate real and reactive power

MW := 1000kW MVA := MW MVAR := MW

- Phasor form first:

$$V_a := V_{mag} \cdot e^{j \cdot 0 \text{deg}}$$

$$I_a := I_{mag} \cdot e^{-j \cdot 30 \text{deg}}$$


$$P_{3ph} := 3 \cdot \text{Re}(V_a \cdot \bar{I}_a) \quad P_{3ph} = 19.486 \text{ MW}$$

$$Q_{3ph} := 3 \cdot \text{Im}(V_a \cdot \bar{I}_a) \quad Q_{3ph} = 11.25 \text{ MW}$$

- Now in DQ reference frames:

$$P_{0dq}(t) := \frac{3}{2} \cdot (V_{0dq}(t)_0 \cdot I_{0dq}(t)_0 + V_{0dq}(t)_1 \cdot I_{0dq}(t)_1 + V_{0dq}(t)_2 \cdot I_{0dq}(t)_2)$$

- Note: we need the 3/2 term because of 2/3 constant in transformation matrix.
- This will differ if use SQRT(2/3)



2/1/17
137

$$V_q \cdot I_d - V_d \cdot I_q$$

$$Q_{0dq}(t) := \frac{3}{2} \cdot (V_{0dq}(t)_2 \cdot I_{0dq}(t)_1 - V_{0dq}(t)_1 \cdot I_{0dq}(t)_2)$$

- Note: we need the 3/2 term because of 2/3 constant in transformation matrix.
- This will differ if use SQRT(2/3)

