University of Idaho

ECE 421
Introduction to Power Systems

Session 19


P1
P2
P3
SW
x.x.x.12
x.x.x.10
IED
IED
IED
IED
P1
P2
P3
PC
X
P4
P5
P6
IED
HACKER

L19 2/2

PRP = Parallel Redundancy Protocol



HSR Highavaliabity Seamless Ring